



# YANMAR®

**YANMAR MARINE USA CORP.**

101 INTERNATIONAL PARKWAY

ADAIRSVILLE, GA

30103

TELEPHONE

(770) 877-9894

FAX

770-877-7565

## MARINE SERVICE ADVISORY

WEBSITE [WWW.YANMARMARINE.COM](http://WWW.YANMARMARINE.COM)

---

### Advisory Number: MSA08-003

---

**DATE:** February 8, 2008  
**TO:** All Marine Distributors, Dealers and OEMs  
**SUBJECT:** Gear in Neutral While Sailing  
**MODELS:** All Sailboat Engines

We continue to get questions regarding the correct gear position while sailing with the engine OFF. This advisory is issued as a reminder; Yanmar requires that if sailing with the engine OFF (not running) the transmission shifter must be in the neutral position or internal damage to the gear or sail-drive will result. This damage will not be covered by Yanmar's Limited Warranty. Please instruct customers and dealers who deliver the sailboat to the customer, of the correct (Neutral) position for the marine gear while sailing.

If the customer desires that the propeller shaft not spin while sailing, either a folding propeller, shaft break, or other suitable device may be used. However, Yanmar accepts no responsibility for the selection, installation, or operation of such devices. Please also refer to Marine service advisory "MSA07-001\_Yanmar Sail Drive Propeller Selection" for additional information.

If you have any questions regarding this advisory please contact a Customer Support Representative at (770) 877- 9894.